

Pavement Condition Index - PCI Measured Values for the Year 2002

Northway Airport

Apron/Taxiway
[4100-01]


Runway 4-22
[6100-01]

Note:
PCIS reflect status of airport pavements prior to the November 2002 earthquake. All airport pavements were destroyed during this earthquake.

Airport Code: ORT
Site No.: 50544.*A

85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Reconstruction
40 - 54	Reconstruction
25 - 39	Reconstruction
10 - 24	Reconstruction
0 - 9	Reconstruction

[] Branch - Section Identifier
Minimum PCI for Runways = 70
Minimum PCI for Taxiways = 60



Pavement Condition Index - PCI Measured Values for the Years 2003-2007

Northway Airport

